




Black and Decker Pivot Plus PD600 Circuit Board Replacement

This guide describes how to replace the circuit board in a Black and Decker Pivot Plus PD600 power drill.

Written By: Mason Garcia



INTRODUCTION

Electrical shorts occur when the circuit board is not connected completely to the drill wires. This may be the result of incomplete or faulty soldering.

This guide provides step by step instruction for resoldering the drill wires to the circuit board.



TOOLS:


- [Phillips #1 Screwdriver](#) (1)
 - [Soldering Workstation](#) (1)
-

Step 1 — Drill




- Remove the nine 15mm Philips #1 screws
- Remove the two 12.5mm Philips #1 screws
- Remove the two 10mm Philips #1 screws

Step 2





- Lift one side of the drill casing off of the drill. Note that the drill casing consists of two pieces on either side of the drill.

Step 3 — Circuit Board



- Carefully grip the circuit board on the exposed edge and lift it away from the drill as far as is possible.
- Make note of where each wire connects on the circuit board.

Step 4



- Starting from the most accessible wire, desolder the wires from the circuit board one by one.
 - Make sure that the tip of the soldering iron is clean of all residue before starting.
 - Heat the soldering iron only to the temperature required to melt the solder. Check the specifications on your spool of solder for the correct temperature.
- Once all of the wires have been desoldered from the circuit board, remove the circuit board completely from the drill.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-09-20 12:55:43 PM.